



All AD620s were removed, and their jumpers jumpered.

All AD797s were replaced with OP27s.

S/N: 110

Daniel Busby Sept. 21, 2006

Change Summary:
On 9 Jan 2001 the associated PCB was changed to reflect the modifications made to this schematic. Pins 6 and 7 on each of the db15 connectors was swapped to cure a schematic error. The schematic is now correct and the REV 'B' circuit board is the current one. The original three schematics were condensed into one due to problems with the netlist.

